
As-Built Report for the East River, Highway 103, HADD Compensation Project (DFO HADD Authorization 04-G8-050): Fish Ladder and Culvert Baffles



Dr. Bob Pett, Environmental Services
October 2006

East River HADD Compensation Project



Downstream end of the box culvert at the Highway 103 crossing, April 2004. During lower flow periods, fish passage is severely compromised or not possible to the upper 845 ha of the East River Watershed.

- involved the extension of the upper end of the box culvert with a 30.5 m-long, three-sided, cast-in-place concrete structure that spanned the stream and preserved the stream bed (new box is 9.1 m-wide and 3.0 m high).
- 7 baffles were retrofit inside the old 3.64 m-wide, 3.04 m high, 60 m-long, box culvert in August-September 2005 (ensures ~25 cm water depth for fish passage through the old culvert).
 - Fish ladder with 4 boxes and a new plunge pool were completed at the downstream end of the culvert in October 2005.

East River HADD Compensation Project





Diagram from Dillon Consulting Limited, 2005, Environmental Screening of Watercourse Crossings for the Highway 103 Twinning Project – East River Watershed, Halifax Regional Municipality.

Construction of the box culvert extension, August-September 2005





Construction of fish baffles in the East River culvert



- 7 baffles constructed inside the existing culvert (one at the downstream end and six more at +6 m, +12 m, +24 m, +36 m, +48 m, and the upper end of the culvert at +60 m; followed the recommendations of Bob Rutherford, TPW consultant, and Henry Caracristi, DFO).
- Baffles are 500 mm high with notches 500 mm wide and 250 mm deep.

September 2, 2005




Baffle formwork; September 2, 2005

(hoses were used to convey the East River flow through the construction site; flow dammed upstream and water pumped as required to maintain water control)



Baffles complete, September 29, 2005

Fish Ladder Design for the East River HADD Compensation Project






Fish ladder complete, September 29, 2005

Fishway boxes were cleaned and a new plunge pool built prior to returning water flow to the stream channel







Storm flow conditions at the fishway on October 13, 2005

One year later – functioning well; high flow periods over the year had re-distributed the surge rock that buttressed the upper fishway box and formed the upper margin of the plunge pool (October 28, 2006)