

## Nova Scotia Department of Transportation and Infrastructure Renewal

2007-2008 Heating Season Radon Results

| <b>Number of Buildings Tested</b>  | <b>less than 200 Bqjm<sub>3</sub></b> | <b>between 200 Bqjm<sub>3</sub> &amp; 600 Bqjm<sub>3</sub></b> | <b>more than 600 Bqjm<sub>3</sub></b> |
|--|---------------------------------------|--|---------------------------------------|
| NSTIR Highway Operations Bases & Offices<br>34   | 33                                    | 0  | 1*                                    |
| <i>*NSTIR Operations Area Office &amp; Garage, 18 Hardscratch Road, Yarmouth – measurement was 1098 Bqjm<sub>3</sub></i> |                                       |  |                                       |
| Provincial Buildings Tested by NSTIR<br>5  | less than 200 Bqjm <sub>3</sub><br>5  | between 200 Bqjm <sub>3</sub> & 600 Bqjm <sub>3</sub><br>0     | more than 600 Bqjm <sub>3</sub><br>0  |
| Court Houses Tested by NSTIR<br>4  | less than 200 Bqjm <sub>3</sub><br>4  | between 200 Bqjm <sub>3</sub> & 600 Bqjm <sub>3</sub><br>0     | more than 600 Bqjm <sub>3</sub><br>0  |
| Tourism Culture and Heritage Buildings Tested by NSTIR<br>32   | less than 200 Bqjm <sub>3</sub><br>32 | between 200 Bqjm <sub>3</sub> & 600 Bqjm <sub>3</sub><br>2 *   | more than 600 Bqjm <sub>3</sub><br>0  |

*\*Grist Mill, 660 Matheson Brooke Road, Balmoral Mills- measurement was 273.8 Bqjm<sub>3</sub>*

*Steam Mill, 3169 326 Route, Denmark- measurement was 259 Bqjm<sub>3</sub>*

