

Appendix 12: Photo Record



Photo 1: Entrance of access road to Spicer Quarry from Highway 1. The active and proposed quarry are located at the top of the north mountain in the distant portion of the photo. Note stone cover on the access road to limit tracking of dirt onto Highway 1, and old field habitat.



Photo 2: View from the quarry access road near the top of the north mountain southward toward Highway 1 and the Annapolis River. Stockpile/Crusher area is visible in center right of the image, as is the access road leading to Highway 1 in the distance. The OHV access road connecting the stockpile/crusher area to the active quarry is visible in the foreground image left.



Photo 3: Active quarry looking northeastward toward Wetland 1. January 2020. The proposed expansion footprint is to the top left corner of the image.



Photo 4: Existing stockpile/Crusher area on the valley floor looking southward from northern extent and the designated crushing area. Temporary asphalt plant designated area is by the excavator in the distance, and weigh scales are image left of the stockpiles located in the image center.



Photo 5: Material stockpiled and signed at the stockpile/crusher area at the base of the mountain, viewed northward toward the mountain slope forested habitat.



Photo 6: View of the weigh scale and scale house northward toward the north mountain slope.



Photo 7: Signage within the OHV portion of the access road at the base of the steep north mountain slope leading to the quarry area.



Photo 8: Forest habitat on the north mountain slope adjacent to the OHV access road between the stockpile/crusher area and existing quarry footprint.



Photo 9: Forest habitat south of Wetland 1 and north of the existing quarry.



Photo 10: View southward toward the Annapolis Valley from a portion of the future quarry footprint. Regenerating mixed wood habitat. Photo from Davis MacIntyre & Associates Ltd. report.



Photo 11: Wetland 1 outflow at fall high flow (Oct. 2019)



Photo 12: Field staff completing quadrat monitoring of vegetation in Wetland 1, June 2015.



Photo 13: Wetland 3, western open bog area (Sept. 26, 2019). Note blue cap of shallow monitoring well in foreground.



Photo 14: Forested eastern portion of Wetland 3, June 2019. Multiple SAR/SOCI were noted in and around Wetland 3.



Photo 15: Ray Brook downstream of the OHV access road within electrofishing reach where Brook trout and American eel were captured. April 2018 image.



Photo 16: Ray Brook in April 2017 upstream of OHV access road, corresponds to the 2019 electrofishing reach where Brook trout were captured.



Photo 17: Groundhog in quarry rock pile, April 2018.