

APPENDIX C
ROCK SULPHUR CONTENT ANALYSIS RESULTS

Environmental Assessment Registration
Document for Seabrook Quarry Expansion
Seabrook, Digby County, Nova Scotia

9-Jul-15

Dexter Construction Co. Ltd.
927 Rocky Lake Drive
P.O. Box 48100
Bedford, NS
B4A 3Z2
Attention: Gavin Isenor

Re: Results of analysis on submitted samples.

<u>Sample</u>	<u>Wt. %</u>	<u>kg/t</u>
	<u>S(Total)</u>	<u>Acid Prod. Potential</u>
Dexter Seabrook Quarry	0.018	0.56
Dexter Seabrook Quarry-DUP	0.019	0.58

<u>Certified Ref. Sa.</u>	<u>Wt. %</u>
	<u>S(Total)</u>
NBM-1 (0.28% S)	0.285

Daniel Chevalier, MAsC
Manager, Minerals Engineering Centre